

W24 0 / W\_24  
W16 0 / W\_16  
W8 0 / W\_8  
IN / ---

W27 0 / W\_27  
W19 0 / W\_19  
W11 0 / W\_11  
W3 0 / W\_3

+12V  
GND  
-12V

W29\_0 / W\_29  
W21\_0 / W\_21  
W13\_0 / W\_13  
W5\_0 / W\_5  
W31\_0 / W\_31  
W23\_0 / W\_23  
W15\_0 / W\_15  
W7\_0 / W\_7

Walsh 32  
V 1.2.0-B / 2023\_04  
www.haraldswerk.de

W\_24 / W\_16  
W\_25 / W\_17  
W\_26 / W\_18  
W\_27 / W\_19  
W\_28 / W\_20  
W\_29 / W\_21  
W\_30 / W\_22  
W\_31 / W\_23

W24-32  
W16-23  
W8-15  
W1-7

W\_8 / ---  
W\_9 / W\_1  
W\_10 / W\_2  
W\_11 / W\_3  
W\_12 / W\_4  
W\_13 / W\_5  
W\_14 / W\_6  
W\_15 / W\_7

W26 0 / W\_26  
W18 0 / W\_18  
W10 0 / W\_10  
W2 0 / W\_2  
W25 0 / W\_25  
W17 0 / W\_17  
W9 0 / W\_9  
W1 0 / W\_1

W1-7  
W1-15  
W1-23  
W1-31  
W28\_0 / W\_28  
W20\_0 / W\_20  
W12\_0 / W\_12  
W4\_0 / W\_4  
W30\_0 / W\_30  
W22\_0 / W\_22  
W14\_0 / W\_14  
W6\_0 / W\_6

