

W24 0 / W_24
W16 0 / W_16
W8 0 / W_8
IN / ---

W27 0 / W_27
W19 0 / W_19
W11 0 / W_11
W3 0 / W_3

+12V
GND
-12V

W29_0 / W_29
W21_0 / W_21
W13_0 / W_13
W5_0 / W_5
W31_0 / W_31
W23_0 / W_23
W15_0 / W_15
W7_0 / W_7

Walsh 32
V 1.2.0-B / 2023_04
www.haraldswerk.de

W_24 / W_16
W_25 / W_17
W_26 / W_18
W_27 / W_19
W_28 / W_20
W_29 / W_21
W_30 / W_22
W_31 / W_23

W24-32
W16-23
W8-15
W1-7

W_8 / ---
W_9 / W_1
W_10 / W_2
W_11 / W_3
W_12 / W_4
W_13 / W_5
W_14 / W_6
W_15 / W_7

W26 0 / W_26
W18 0 / W_18
W10 0 / W_10
W2 0 / W_2
W25 0 / W_25
W17 0 / W_17
W9 0 / W_9
W1 0 / W_1

W1-7
W1-15
W1-23
W1-31
W28_0 / W_28
W20_0 / W_20
W12_0 / W_12
W4_0 / W_4
W30_0 / W_30
W22_0 / W_22
W14_0 / W_14
W6_0 / W_6

